充磁方向 Directions of Magnetization



S









厚度方向充磁

oriented through thickness

轴向充磁


axially oriented

轴向多极充磁

axially oriented














表面多极充磁

oriented laterally multipole on one face




表面多极充磁

multipole oriented in seaments on outside diameter multipole oriented in segments on one face





radially oriented




径向充磁

oriented thtough diameter





multipole oriented in segments on inside diameter











diametrical oriented